



US g.p.m.

Imp. g.p.m.

feet

150

100

50

0

l/min

m³/h

Поддача Q ▶

Напор H (метры) ▶

50

40

30

20

10

0

0

5

10

15

20

0

5

10

15

20

0

5

10

15

20

25

30

35

40

45

50

0

0.5

1

1.5

2

2.5

3

CK90E

CK80E

CK50

CK50BP